

Clean axle tubes for welding.
 Set axle at proper pinion angle.
 Bolt joint into lower control arm mounts.
 Locate lower control arm mount on axle.

Weld outside of both mounts.


Locate spring perches. Weld around axle tube.


8) Locate spring bucket plate.
9) Make three 1" welds around plate.
10) Locate lower shock mounts.

11) Weld three sides to axle tube.

12) Locate truss on axle.

13) Weld four sides, both ends to axle tubes.





TITLE:

XJ Rear Coil Conversion Axle Bracket Kit (3.00" Tube)

SIZE DWG. NO.

1201130

Α

REV

SCALE: 1:12 WEIGHT:

SHEET 1 OF 4

